


Menu**HISTORY FILE MAP for year 2001**

Realtime

Playback

Recalled Realtime

Recalled Playback



DSS43 accumulator pump stoppage caused antenna halt losing 11m RT 1024bps data. Subsequent Tx off caused a further 5m loss of RT 1024bps data due to additional s/c transition from 1-way to 2-way (2-way to 1-way change went smoothly). DR A05068 refers.